

2019 TowerJazz MPW Schedule

| | Fab | | Tape-In |
|---|---------------|--|----------------------|
| SB*18 B3713 | NPB - Fab 3 | SiGe BiCMOS 0.18um | 11/13/18 |
| <i>Please contact your sales representative for information on fast track processing.</i> | | | |
| CA18 B3714 | NPB - Fab 3 | RFCMOS 0.18um | 12/04/18 |
| <i>Please contact your sales representative for information on fast track processing.</i> | | | |
| SB*18 B3900 | NPB - Fab 3 | SiGe BiCMOS 0.18um | 01/08/19 |
| <i>Please contact your sales representative for information on fast track processing.</i> | | | |
| CA18 B3901 | NPB - Fab 3 | RFCMOS 0.18um | 02/05/19 |
| <i>Please contact your sales representative for information on fast track processing.</i> | | | |
| 7th MPW Uozu, Japan | TPSCo - Fab 7 | CMOS & PM & RFCMOS 65nm | 02/28/19 |
| SB*18 B3903 | NPB - Fab 3 | SiGe BiCMOS 0.18um | 03/05/19 |
| <i>Please contact your sales representative for information on fast track processing.</i> | | | |
| 8th MPW Uozu, Japan | TPSCo - Fab 7 | RFSOI 65nm | 03/29/19 |
| CS18* B3905 | MH - Fab 2 | CMOS-SOI 0.18um includes CS18QT9 | 04/16/19 |
| SB*18 B3906 | NPB - Fab 3 | SiGe BiCMOS 0.18um | 04/30/19 |
| <i>Please contact your sales representative for information on fast track processing.</i> | | | |
| SH219T18MAY | MH - Fab 2 | CIS 0.18um, 0.11um Image Sensor CMOS+ 0.16um, 0.18um RF, RFID, PM | 05/13/19 05/20/19 |
| CA18 B3907 | NPB - Fab 3 | RFCMOS 0.18um | 05/14/19 |
| <i>Please contact your sales representative for information on fast track processing.</i> | | | |

2019 TowerJazz MPW Schedule

| | Fab | | Tape-In |
|---------------------------|---|-------------------------------------|----------|
| PH18MA B3908 | NPB - Fab 3 | SiPho 0.18um | 05/28/19 |
| SB*18 B3909 | NPB - Fab 3 | SiGe BiCMOS 0.18um | 06/25/19 |
| | <i>Please contact your sales representative for information on fast track processing.</i> | | |
| 10th MPW Tonami, Japan | TPSCo - Fab 5 | CMOS 0.18u & 0.16u, PM, PM_SOI | 06/28/19 |
| SH119T11JUL | MH - Fab 2 | CIS 0.11um Image Sensor | 07/08/19 |
| 9th MPW Uozu, Japan | TPSCo - Fab 7 | CMOS & PM & RFCMOS 65nm | 07/19/19 |
| SH319T18AUG | MH - Fab 2 | CIS 0.18um, 0.11um Image Sensor | 08/05/19 |
| | | CMOS+ 0.16um, 0.18um RF, RFID, PM | 08/12/19 |
| PH18MA B3910 | NPB - Fab 3 | SiPho 0.18um | 08/13/19 |
| SB*18 B3911 | NPB - Fab 3 | SiGe BiCMOS 0.18um | 09/03/19 |
| | <i>Please contact your sales representative for information on fast track processing.</i> | | |
| CS18* B3912 | MH - Fab 2 | CMOS-SOI 0.18um includes CS18QT9 | 09/17/19 |
| 11th MPW Tonami, Japan | TPSCo - Fab 5 | CMOS 0.18u & 0.16u, PM, PM_SOI | 09/20/19 |
| PH18MA B3913 | NPB - Fab 3 | SiPho 0.18um | 10/08/19 |
| SH219T11OCT | MH - Fab 2 | CIS 0.11um Image Sensor | 10/22/19 |

2019 TowerJazz MPW Schedule

| | Fab | | Tape-In |
|---|---------------|------------------------------------|----------|
| SB*/CA/13* B3914 | NPB - Fab 3 | SiGe BiCMOS/RF CMOS 0.13um | 10/22/19 |
| <i>Please contact your sales representative for information on fast track processing.</i> | | | |
| SH419T18NOV | MH - Fab 2 | CIS 0.18um, 0.11um Image Sensor | 11/04/19 |
| | | CMOS+ 0.16um, 0.18um RF, RFID, PM | 11/11/19 |
| 10th MPW Uozu, Japan | TPSCo - Fab 7 | CMOS & PM & RFCMOS & RFSOI 65nm | 11/29/19 |
| SB*18 B3916 | NPB - Fab 3 | SiGe BiCMOS 0.18um | 11/12/19 |
| <i>Please contact your sales representative for information on fast track pr</i> | | | |
| CA18 B3917 | NPB - Fab 3 | RFCMOS 0.18um | 12/03/19 |
| <i>Please contact your sales representative for information on fast track processing.</i> | | | |

Notes :

"Shuttles" (SH*) are run at Fab 2

* 0.13u MH - fab 2 Shuttle / MPW slots will be considered per needs

Please contact your customer account manager for additional information.

Fab2 -- TowerJazz 200mm wafer fabrication facility at Migdal Ha'emek, Israel

Fab3 -- TowerJazz 200mm wafer fabrication facility at Newport Beach, CA

Fab5 -- TowerJazz 200mm wafer fabrication facility at Tonami, Japan

Fab7 -- TowerJazz 300mm wafer fabrication facility at Uozu, Japan